

Annex B30:USAR Team Post-Mission Report Form

USAR Team Post-Mission Report Form



Post Mission Report is recommended to be completed and submitted to the INSARAG Secretariat within 45 days following every national or foreign USAR deployment. If possible, include a photographic record of the mission with the report submission.

Below is an outline of the contents this report should address.

Team Name	PMKMSZ - PEST COUNTY SEARCH AND RESCUE SERVICE (HUN – 10)
Mission	Turkey & Syria Earthquake (6 February 2023)
Overview	<ul style="list-style-type: none"> - On Feb. 6, a magnitude 7.8 earthquake occurred in southern Turkey near the northern border of Syria. This quake was followed approximately nine hours later by a magnitude 7.5 earthquake located around 95 kilometers to the southwest.
Preparation	<ul style="list-style-type: none"> - 04:51: First EQ Alert Message received from GDACS to the Team Leader (TL) mobile phone. (Team Monitoring the Situation on V.O) - 08:07: HUNOR (HUN-1) and HUSZAR (HUN-2) in Stand-by. - 12:36: HUNOR (HUN-1) started mobilizing, HUSZAR stand-by cancelled. PMKMSZ (HUN-10) asked permission to travel from focal point. Contact with Ministry of Foreign Affairs & Trade and Turkish Embassy. - 15:06 Alert sent out to team members, welcome letter received from Turkish Embassy. - 20:20 HUN-10 with 22 people, 4 rescue dogs and 1.5t of equipment departed for Istanbul on Turkish Airlines flight
Mobilization	<p>07/02/2023</p> <p>4:30 Departure for Adana</p> <p>6:45 Arrival in Adana, check-in at RDC. With the help of AFAD and the Embassy, arrange a bus for transportation</p> <p>9:20 Departure Antakya, Hatay</p> <p>14:30 Arrive BoO at Hatay Expo, contact BoO manager and UCC (NED-1)</p>
Operations	<p>07/02/2023</p> <p>15:54 Departure first worksite</p> <p>16:17 Arrival at the first worksite (Q sector, no worksite ID) (ASR2) 36.203142, 36.151000 (ASR2): dog signal 2 live victims under light brick rubble, we asked for the help of the locals to rescue them</p> <p>19:20 Arrival at second worksite (K sector) (ASR 2) 36.201210, 36.147691 - 36.203253, 36.148916</p> <p>300m road section on both sides, total of 24 buildings searched, 8 buildings totally collapsed, 13 confirmed live victims at 5 different locations.</p> <p>Triage A, UCC via request for assistance to recover.</p> <p>2 victims recovered.</p>

	<p>08/02/2023 1:37 Arrival of NED-2 17:30 Arrival of Slovak Mountain Rescue Team 1 live victim only recovered by heavy team, team departs for next worksite.</p> <p>09/02/2023 8:21 Arrival to M2 worksite (36.212699, 36.140434): 2 confirmed live victim 9:10 2 live victims recovered Request from the UCC to review 4 other worksites, no live victims</p> <p>10/02/2023 Reviewing another worksites for UCC request 9:20 X-2 worksite: 36.206354 36.170533 11:57 B-1 worksite: 36.19172 36.16542 12:30 sector F no worksite ID: 36.21799 36.17900 14:18 36.25515 36.19074 16:20 36.24268 36.16258 18:16 Back to BoO 21:35 Helping to NED-1 on 36.22694 36.16246 with search and Doctor</p>
Coordination with LEMA	<ul style="list-style-type: none"> - Coordination with AFAD (LEMA) representatives in the ADANA Airport for JOR-01 transportation requirements (Bus) to the affected areas. - Coworking with National Ambulance Service - Coordination with AFAD in the field & the local authorities in the assigned operation areas & BoO location. - Coordination with LEMA for providing the team with the logistics (Water, Fuel, Translator)
Coordination with OSOCC (UCC)	<ul style="list-style-type: none"> - HUN-10 check-in the RDC in ADANA Airport - Assignments for BoO & worksites locations by UCC and AFAD - Coordination with (HATAY UCC which managed by NED-01), 1 person assigned to UCC. - Coordination with RDC for Demobilization. - All related DATA submitted on the V.O and on the ICMS, but in the first days internet connection is unstable and satellite phones aren't worked.
Coordination with other teams	<ul style="list-style-type: none"> - Coordination with Nederland, Switzerland and Slovakian teams and use same BoO location. - Coordination with AKUT team and AFAD.
Base of Operation	<ul style="list-style-type: none"> - HUN-10 BoO located in Antakya - Hatay Expo - BoO Coordinates (36.241299, 36.110611)

Team Management	<ul style="list-style-type: none"> - HUN-10 Management Unit: Team Leader + Deputy Operation Logistic Doctor Search Liaison Officer
Logistics	<ul style="list-style-type: none"> - Light BoO - 1,5 tons of Equipments
Search	<ul style="list-style-type: none"> - 6 personnel (4 K9 Handler + 2 search technician), - 4 Search Dogs - Search Cameras + Acoustic Devices.
Rescue	<ul style="list-style-type: none"> - Light Rescue Equipments - 16 Rescuers
Medical	<ul style="list-style-type: none"> - 1 Doctor
Demobilization	<ul style="list-style-type: none"> - HUN-10 Demobilization phase starts on 11/02/2023 at 5:00. - Demobilization coordinated by HATAY UCC & ADANA Airport RDC. - Departed 14:50 from ADANA Airport. - Arrived home country on 20:30 to Budapest Airport - 23:10 Arrived back to PMKMSZ Base
Lessons Learned	<ul style="list-style-type: none"> - We traveled with a regular plane and we have a limitation of the equipment, but this light equipment isn't enough to operate with a full BoO, and we don't had enough rescue capacity - The Importance of coordination with (LEMA – INSARAG Community – RDC – UCC – Other Teams - Home Country – Embassy in Affected Country).
Recommendations	-
Provider of Information	László Balázs (Team Leader) and Gergely Balázs (Liason Officer)
Contact Details	László Balázs HUN–10 Team Leader Mobile: +36 70 458 7001 E-mail:iroda@kutato-mento.hu

PREPARED BY
Ádám Csordás
Liaison Officer
Pest County Search & Rescue Service
Hungary

APPROVED BY
László Balázs
Team Leader
Pest County Search & Rescue Service
Hungary